

Our response to WCC Highways nomination 2019 – 2020

Parliament Square pavement outside Houses of Parliament – 29th August 2018

The large puddles that form whenever it rains force pedestrians either to skirt the puddle by walking on the main road or to get their feet wet. This is shaming in an area that is heavily used by tourists. The problem is compounded by the squalid crush barriers placed outside the gates, which restrict the width of the pavement.